

1888.



1936.



1980.

SITE AXONOMETRIC

ARCHITECTURAL DESIGN STUDIO FOR RESTORATION OF COMPLEX ARCHITECTURE

Giulio M. Barazzetta Architectural Design
 Angela Pavesi Technology Design in BIM environment
 Rossana Gabaglio Restoration
 Lucia Toniolo Materials for preservation
 Mauro E. Giuliani Structural Design
 Luca Piterà Building services Design

Conceptual Design Proposal:

Our start of design point is to create new space that could reflect the trend of the times and society. So, we tend to draw out some parts of floor to create double high space. As a result, more communication could happen between two different floor. At the same time, in order to keep connection between the existing building and new construction, we would remain the main structure.

The second point is to reinforce structure. In order to solve the problem, we choose to add some braces between columns. At the same time, we have reorganised function. It could fix new structural system well (we can see in the diagram). The brace would be steel and it will be connected with beam and column by screw.

For convenient regulation and better space organisation, we put all educational parts into one side and add some missing functions such as video room, computer room, infirmary, offices for teachers etc.

And then, we move the majority of parking area from ground to underground. As a result, there are more space for children's daily activities.

In addition, we add a layer of insulation for saving energy. To some extent, it is a most remarkable element that could tell the difference between old buildings and modern buildings. Because we want to have a new appearance for the building, we would reconstruct external walls and at the same time, insulation could be a very important part we need to focus on.



MASTERPLAN _ SCALE 1:500




POLITECNICO
MILANO 1863

ARCHITECTURAL DESIGN STUDIO FOR RESTORATION OF COMPLEX ARCHITECTURE
POLITECNICO DI MILANON
SCHOOL OF ARCHITECTURE, URBAN PLANNING AND CONSTRUCTION ENGINEERING
BUILDING ARCHITECTURE
A.Y. 2018-2019

STUDENTS
XIFANGYAN 891924
DOUHAOMING 893079





Rented office

1.Office area	696 m ²
2.Balcony x 3	50 m ²

Rented classroom

1.Classroom x 6	265 m ²
2.Workshop x 4	118 m ²
3.Activity room	60 m ²
4.Office	31 m ²
5.Rest space	31 m ²
6.Corridor	223 m ²

School area

1.Equipment room for school	30 m ²
2.Reception	12 m ²
3.Toilt	29 m ²

Kindergarten

1.Activity room x 2	88 m ²
2.Multi purpose room	44 m ²
3.Storage room	10 m ²
4.Office	14 m ²
5.Morning checkroom	14 m ²
6.Cloakroom	18 m ²
7.Toilt	29 m ²
8.Corridor	106 m ²

Primary school

1.Rest space	42 m ²
2.Activity room	42 m ²
3.Equipment room	28 m ²
4.Classroom x 3	126 m ²
5.Teachers' office	28 m ²
6.Toilt	29 m ²
7.Corridor	117 m ²

Cafeteria

1.Cafe shop	42 m ²
2.Rest space	134 m ²

Exhibition area


1.Office	24 m ²
2.Exhibition area	361 m ²

Technical area

1.Technical	1100 m ²
-------------	---------------------

Toilet

1.Toilet	182 m ²
----------	--------------------









GROUNDFLOORPLAN _SCALE 1:200





First Plan_Scale 1:200




Second Plan_Scale 1:200



Third Plan_Scale 1:200






Section B-B Scale 1: 200



West Elevation Scale 1:200




West Elevation Mapping Scale 1:200












East Elevation Scale 1:200



East Elevation Mapping Scale 1:200







Floor load	Bulk density(kg/m³)	Thickness(mm)	Weight per unit area(KN/m²)
Dead load from slab(structural)	2300.00		2.76
Dead load from slab(no structural)			0.336
wood based subfloor	650	15	0.098
Waterproof-high density polyethylene	950	8	0.076
Cavity insulation	0	0	0
Waterproof-high density polyethylene	950	8	0.076
Gypsum Board	900	9.5	0.086
Live load			4




Floor (not include the struct)	formula	number	unit
$Q_1 = (G_1 + G_2 + G_3) * 1.3 + 1.5 Q$			
G1: Self load of beam	$H_1 * B_1 * 23 \text{ KN/m}^3$	1.15	KN/m
G2: Dead load from slab(structural)	$1.23 * 2.76 \text{ KN/m}^2$	3.39	KN/m
G3: Dead load from slab(non-stru)	$1.23 * 0.336 \text{ KN/m}^2$	0.41	KN/m
Q: live load	$1.23 * 4 \text{ KN/m}^2$	4.92	KN/m
Q1: factored total load on seconds	$Q_2 = (G_1 + G_2) * 1.3 + 1.5 Q$	13.83	KN/m



Check the shear	formula	number	unit
I	$L_{1/2}$	2.75	m
d	$B_{1/2}$	0.08	m
Vmax		38.03	KN
Ved	$V_{ed} = (L-d)/L * V_{max}$	36.99	KN
Vn=Vc+Vs		47.20	KN
	$V_c = 2 * f_{ck} * b * w * d$		
	$V_{c>} > V_{ed}$		

Beam information	number	unit
Floor		
L1: Length of beam	5.50	m
H1: height of beam	0.30	m
B1: width of beam	0.15	m
A1: area of beam	0.05	m²


Check the Moment	formula	number	unit
Med max	Max applied moment	52.28	KNm
Mrd max	Max moment without compression steel	62.63	KNm

Mrd max > Med max







Underground Floor and Ground Floor Structure Plan




Second Floor and Third Floor Structure Plan




There are two junctions between the whole building. So, this building is like three separate buildings from structure view.
However, there are only shear walls on both sides. The first thing we need to consider is to reinforce the middle part of the building.

In order to build the middle staircase, you need to make a hole in the existing floor. After the hole is finished, two reinforced concrete beams are placed in the lateral direction of the U-shaped floor to reinforce the floor.




Section of additional beam


When the hole was cut, some parts were also taken away and exposed internal rebar of beam. And then, the new secondary beams were put there and connected with existing beam to reinforce the slab.




Axonometric view of all services




Axonometric view of rainwater distribution




Ventilation system of a typical room, section




Heating system of a typical classroom



Heating system of a plan






Ventilation system



Water supply system

Discharge system









West elevation

MATERIAL MAPPING LEGEND



- [Red] Aluminium framings and flashings
- [Orange] Zinc coated steel sheets
- [Light Orange] Glass
- [Light Green] Metal panel
- [Dark Green] Steel grids
- [Cyan] Cement mortar
- [Yellow] Steel framings and awnings
- [Purple] Reinforced concrete
- [Dark Purple] Stone step pavings
- [Dark Green] Brick curb of ramp
- [Light Green] Cement plaster with painted finishing
- [Grey] Copper awnings and flashings
- [Dark Purple] Wood with painted coating
- [Green] PVC framings
- [Pink] Tiled surface





Detail A




Detail B-1




Detail B-2




Detail E






4 5 6 7

	Missing part
	Discoloration and Depositsoiling
	Mechanical Damage
	Detachment



4 5 6 7

	Aluminium framings and flashings
	Zinc coated steel sheets
	Glass
	Cement mortar
	Steel framings and awnings
	Reinforced concrete
	Stone step pavings
	Copper awnings and flashings
	Cement plaster with painted finishing



4 5 6 7

	Cleaning the deposit from the plaster mortar.
	Removing the remaining eroded vertical elements made out of reinforced concrete.
	Grouting lime mortar on cracks and detached parts of the surface matching with existing.
	Removal of inappropriate cement mortar from the surface.
	Adding aluminum vertical elements.
	Painting a new layer as coating for protection after cleaning the rust to avoid corrosion.

Guidelines for the conservation:

At the ground floor, we remove most of existing wall to open the space for public and at other floors, we remain all exterior wall to keep spirit of this light machinery building.

On the east side, we do few things about exterior walls because these walls have been repaired once and it works well.

On the west side, we add new windows and walls behind existing windows and walls. Because some parts have peeled off from existing walls, in order to improve the existing walls, we choose add a layer of mortar. For windows, we will remain it and paint them.

For inside space, we choose new floor construction that have inside insulation to replace existing floor. At the same time, indoor walls would be removed and new walls with insulation would be chosen.

Details of conservation

Mortars detachment and cracks of facade

Intervention


Cleaning and removing some parts and then adding the replacement with same materials and color. At first, we can remove and clean the deposits on our surface by brushing. Then the solution is grouting of missing parts, detached and removed parts bay using lime mortar, added with natural pigments in order to acquire the same color with the existing ones on our surface. We can also fill the cracks with lime mortar.



Windows and doors framings, flashings, windowsills

Intervention


Cleaning by hand is the best way to remove thick corrosion layers, working with fine hand-tools and with the aid of a low power microscope. Chemical cleaning maybe is not the best way because it cannot easily be controlled and some chemicals may remain on the object. We have to remove the rust from the steel framings.



Vertical elements

Intervention

Adding the vertical elements with the same material as the refurbished elements. After that, we could follow the original form. It could hide drainage pipes. Also it can help avoid our columns from erosion so it works as a protection.





Expansion joints



Intervention

Removing of the cement mortars at these borders are needed then we can cover the gap with expansion joint system.





14



SECTION A-A SCALE 1:100

