

Chapter 4: Methodologies

Table 4.1. Type of action on a plane surface with the coefficient parameters (<i>Borri, 2011</i>).....	118
Table 4.2. Type of action on a plane surface and the IQM ratios related to the category of the masonry (<i>Borri, 2011</i>).....	118
Table 4.3: Curve of Correlation between fm (min, max values) and vertical IQM (<i>Borri, 2011</i>).....	122
Table 4.4: Curve of Correlation between fm (average value) and vertical IQM (<i>Borri, 2011</i>).....	122
Table 4.5: Curve of Correlation between To (min and max value) and vertical IQM (<i>Borri, 2011</i>)..	123
Table 4.6: Curve of Correlation between To (average value) and vertical IQM (<i>Borri, 2011</i>).....	123
Table 4.7: Curve of Correlation between E (min and max value) and vertical IQM (<i>Borri, 2011</i>)....	124
Table 4.8: Curve of Correlation between E (average value) and vertical IQM (<i>Borri, 2011</i>).....	124
Table 4.9: Proposal of symbolism for the representation of the masonry (<i>Borri, 2011</i>).....	153
Table 4.10: Proposal symbolism for the representation of the structural characteristics and stratigraphic (Structural Discontinuities) (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	156
Table 4.11: Proposal symbolism for the representation of the structural characteristics and stratigraphic (Degradation of structural elements) (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	157
Table 4.12: Proposal symbolism for the representation of the structural characteristics and stratigraphic (Conditions) (<i>Borri, 2011</i>).....	158
Table 4.13: Proposal of symbolism for the representation of the mechanisms of collapse. Each mechanism can be described as a set of actions, and displacements induced damage to the masonry walls (<i>Borri, 2011</i>).....	159
Table 4.14: Proposal symbolism for the representation of the crack and collapse (Description of the effects of the collapse of the construction on the matter (physical damage) (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	161
Table 4.15: Proposal symbolism for the representation of the crack and collapse (Description of the effects of the collapse of the construction on the matter (geometrical modifications) (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	162
Table 4.16: Proposal symbolism for the representation of the crack and collapse (Description of the effects of the collapse of the construction on the matter (Loss of verticality– entities of the ‘tilt’) (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	163
Table 4.17: Mechanism of collapse of the masonry walls with their function of the boundary conditions (<i>Borri, 2011</i>).....	167
Table 4.18: Different failure mechanisms that are subjected to seismic action found in buildings, under vertical loads (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	168
Table 4.19: Different failure mechanisms that are subjected to seismic action found in buildings, under horizontal loads in plane action and horizontal loads out of plane action (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	169
Table 4.20: Different failure mechanisms that are subjected to seismic action found in buildings, under horizontal loads out of plane action (<i>Borri, 2011</i>), (<i>Dogliani, 1999</i>).....	170

Chapter 5: Earthquakes in Anatolia

Table 5.1: Earthquakes during historical periods (2100BC – 1900 AD) in and around znik (<i>Adatepe, Erel 2006</i>).....	177
Table 5.2: Historical earthquakes (<i>Turkey’.T.C. Basbakanlik Afet ve Acil Durum Yönetimi Başkanlı ı, Deprem Dairesi Başkanlı ı</i>).....	185
Table 5.3: Historical earthquakes (<i>Turkey’.T.C. Basbakanlik Afet ve Acil Durum Yönetimi Başkanlı ı, Deprem Dairesi Başkanlı ı</i>).....	186

LIST OF TABLES

Chapter 7: Case Studies

Table 7.1: Qualitative methods for evaluating the quality of the walls in Emirler bath: A.....	239
Table 7.2: Qualitative methods for evaluating the quality of the walls in Emirler bath: B.....	240
Table 7.3: Qualitative methods for evaluating the quality of the walls in Emirler bath: C.....	241
Table 7.4: Qualitative methods for evaluating the quality of the walls in Süleymanpa a bath: A.....	245
Table 7.5: Qualitative methods for evaluating the quality of the walls in Süleymanpa a bath: B.....	246
Table 7.6: Qualitative methods for evaluating the quality of the walls in Süleymanpa a bath: C.....	247
Table 7.7: Damage analysis of “Süleymanpa a” case study bath structure, “Cell A”	249
Table 7.8: Damage analysis of “Süleymanpa a” case study bath structure, “Cell B”.....	250
Table 7.9: Damage analysis of “Süleymanpa a” case study bath structure, “Cell C”	251
Table 7.10: Damage analysis of “Süleymanpa a” case study bath structure, “Cell D, C” elevation.....	252
Table 7.11: Damage analysis of “Süleymanpa a” case study bath structure, “Cell C, B, A” elevation.....	253
Table 7.12: Collapsed analysis of “Süleymanpa a” case study bath structure, Section A-A.....	254
Table 7.13: Qualitative methods for evaluating the quality of the walls in smail Bey bath: A	257
Table 7.14: Qualitative methods for evaluating the quality of the walls in smail Bey bath: B.....	258
Table 7.15: Qualitative methods for evaluating the quality of the walls in smail Bey bath: C.....	259
Table 7.16: Damage analysis of “ smail Bey” case study bath structure, “Cell A”	261
Table 7.17: Damage analysis of “ smail Bey” case study bath structure, “Cell B”	262
Table 7.18: Damage analysis of “ smail Bey” case study bath structure, “Cell C”	263
Table 7.19: Damage analysis of “ smail Bey” case study bath structure, “Cell D”	264
Table 7.20: Damage analysis of “ smail Bey” case study bath structure, “Cell E”	265
Table 7.21: Collapsed analysis of “ smail Bey” case study bath structure, Section A-A	266
Table 7.22: Collapsed analysis of “ smail Bey” case study bath structure, Section B-B / C-C / D-D	267
Table 7.23: Qualitative methods for evaluating the quality of the walls in Beylerbeyi bath: A	270
Table 7.24: Qualitative methods for evaluating the quality of the walls in Beylerbeyi bath: B.....	271
Table 7.25: Qualitative methods for evaluating the quality of the walls in Beylerbeyi bath: C.....	272
Table 7.26: Qualitative methods for evaluating the quality of the walls in Gazi Mihal Bey bath: A	276
Table 7.27: Qualitative methods for evaluating the quality of the walls in Gazi Mihal Bey bath: B	277
Table 7.28: Qualitative methods for evaluating the quality of the walls in Gazi Mihal Bey bath: C	278
Table 7.29: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell A”	280
Table 7.30: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell B”	281
Table 7.31: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell C”	282
Table 7.32: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell D”	283
Table 7.33: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell E”	284
Table 7.34: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell F”.....	285
Table 7.35: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell K”	286
Table 7.36: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell B, A, K” elevation	287
Table 7.37: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell E, D, C, B” elevation	288

LIST OF TABLES

Table 7.38: Damage analysis of “Gazi Mihal Bey” case study bath structure, “Cell K, J, I, H” elevation	289
Table 7.39: Collapsed analysis of “Gazi Mihal Bey” case study bath structure, Section A-A	290
Table 7.40: Collapsed analysis of “Gazi Mihal Bey” case study bath structure, Section B-B / C-C.....	291
Table 7.41: Qualitative methods for evaluating the quality of the walls in Havsa Sokollu bath: A ..	295
Table 7.42: Qualitative methods for evaluating the quality of the walls in Havsa Sokollu bath: B ..	296
Table 7.43: Qualitative methods for evaluating the quality of the walls in Havsa Sokollu bath: C ...	297
Table 7.44: Qualitative methods for evaluating the quality of the walls in Ke an bath: A	300
Table 7.45: Qualitative methods for evaluating the quality of the walls in Ke an bath: B	301
Table 7.46: Qualitative methods for evaluating the quality of the walls in Ke an bath: C	302
Table 7.47: Damage analysis of “Ke an” case study bath structure, “Cell A”	304
Table 7.48: Damage analysis of “Ke an” case study bath structure, “Cell B”	305
Table 7.49: Damage analysis of “Ke an” case study bath structure, “Cell C”	306
Table 7.50: Damage analysis of “Ke an” case study bath structure, “Cell C, D, E” elevation.....	307
Table 7.51: Damage analysis of “Ke an” case study bath structure, “Cell C, B, E” elevation.....	308
Table 7.52: Damage analysis of “Ke an” case study bath structure, “Cell F”	309
Table 7.53: Collapsed analysis of “Ke an” case study bath structure, Section A-A.....	310
Table 7.54: Collapsed analysis of “Ke an” case study bath structure, Section B-B / C-C.....	311
Table 7.55: Qualitative methods for evaluating the quality of the walls in Yeniçeri bath: A	314
Table 7.56: Qualitative methods for evaluating the quality of the walls in Yeniçeri bath: B	315
Table 7.57: Qualitative methods for evaluating the quality of the walls in Yeniçeri bath: C	316

Chapter 8: Conclusion

Table 8.1: Comparison table of the bath structures and their specifications with reference of chapters and pages.....	320
---	-----